Gold Crown Residential and Commercial Inspections

133 County Road 655, Brazoria, TX 77422

(888) 872-9192

Web: goldcrowninspections.com email: donnie@ goldcrowninspections.com



This Professional Inspection Report Has Been Prepared Exclusively For:

Sample Report Inspection Address Inspection City TX ZipCode

Inspector: Donnie Thomas TREC#25486



PROPERTY INSPECTION REPORT FORM

Sample Report (555) 555-5555 Name of Client	Nov 14, 2022 Date of Inspection	
Inspection Address, Inspection City, TX ZipCode Address of Inspected Property		
Donnie Thomas	<u>25486</u> TREC License #	
Name of Sponsor (if applicable)	TREC License #	

PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. *It is important* that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

RESPONSIBILTY OF THE INSPECTOR

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minim um requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component OR constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- · provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

RESPONSIBILTY OF THE CLIENT

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

REPORT LIMITATIONS

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices and arc-fault (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Property inspected wa	IS:	Parties present at inspection:
Real Estate Office:		Selling Agent:
House information:	Approx. Sq. Ft Null	Approx. Yr Built Null

Page 3 of 16

Prepared exclusively for **Sample Report** • by **Donnie Thomas TREC#25486**

© 2022 Gold Crown Residential and Commercial Inspections • (888) 872-9192• goldcrowninspections.com Web:

Weather Condition at Time of Inspection

Weather Condition during inspection:

Outside temperature at Arrival: [##]° Cost of inspection services: <u>\$#, 0.00</u> Complaint Form 203-6-17 3.pdf

Outside temperature at Departure: [##]° paid at: CLIK **Consumer Notice**

Important Limitations and Disclaimers

This Property Inspection Report reports on only the items listed and only on the current condition of those items as of the date of inspection. This report reflects only if the items inspected are observed to be "operable" or "inoperable" at the time of inspection; that is whether such items are observed to serve the purpose for which they are ordinarily intended, at this time. This report reflects only those items that are reasonably observable at the time of inspection. NO RERPRESENTATION OR COMMENT is made concerning any latent defect or defects not reasonably observable at the time of the inspection or of items which require the removal of major or permanent coverings. For example, but without limitation, recent repairs, painting or covering may conceal prior or present leak damage which is not reasonably observable by the inspector and no representation or comment can be made. NO REPRESENTATION IS MADE CONCERNING ANY OTHER CONDITION OR THE FUTURE PERFORMANCE OF ANY ITEM. NO REPRESENTATION IS MADE AS TO ITEMS NOT SPECIFICALLY COMMENTED UPON. ALL WARRANTIES, EXPRESSED OR IMPLIED, NOT SPECIFICALLY STATED HEREIN ARE EXCLUDED AND DISCLAIMED. If a comment is made concerning the condition of any item, the Client is URGED to contact a qualified SPECIALIST to make further inspections or evaluations of that item. Client must notify Gold Crown Residential and Commercial Inspections in writing of any complaints within seven (7) days of the date of inspection and must thereafter allow prompt re-inspection of the item in question. Otherwise, all claims for damages arising out of such complaint are waived by Client. If Client institutes any legal action concerning this inspection, and fails to prevail on all causes of action alleged, Client shall be liable to Gold Crown Residential and Commercial Inspections for all of its attorney's fees incurred in such action. Actual damages for any breach of contract or warranty, negligence or otherwise are limited to the amount of the inspection fee paid. The Client, by accepting this Report or relying upon it in any way, expressly agrees to these Limitations and Disclaimers.

For more information concerning your rights, contact the Consumer Protection Division of the Attorney General's Office, your local District or County Attorney, or the attorney of your choice.

I FULLY and COMPLETELY understand that this inspection is not a warranty or guarantee. This inspection is essentially visual, it is not technically exhaustive, and it does not imply that every defect will be discovered. It is only a statement of opinion and/or condition as of and on this date.

CLIENT SIGNATURE: _____ DATE: _____

INSPECTED BY: Donnie Thomas TREC#25486

cation: Inspection Address Inspection City TX ZipCode	Page 5 of 16
NI=Not Inspected NP=Not Present D=Deficient	
Crawl Space inspected from:	
•	mediete eignifieent
	imediate significant
Prior to closing, the foundation should be inspected by a qualified structure	ral engineer, familiar
with the soils and construction methods of the region, in order to determine	ne if permanent
repairs are required.	
Additional Notes (An opinion on performance is mandatory):	
Comments:	
□No evidence of water penetration observed at this time	
Additional Notes:	
C. Roof Covering Materials	
Type(s) of Roof Covering:	
Viewed From:	
	staples exposed
Additional Notes: (This inspector is not a roofing expert. Client should have	a roofing company
inspect the roof for further evaluation if the Client so chooses)	
Attic Ventilation Type:	
Gutters: Bent Sections Debris	
Downspouts: Missing Extension/splash block missing	
Attic	
Attic Insulation:	
	NIENd Inspected NP=Not Present D=Deficient I. STRUCTURAL SYSTEMS A. Foundations Type of Foundation(s): Comments: (If all crawl space areas are not inspected, provide an explanation.) Crawl Space inspected from: Performance Opinion: At this time, the foundation appears to be supporting the structure and intrepair needs are not evident. Prior to closing, the foundation should be inspected by a qualified structur with the soils and construction methods of the region, in order to determine repairs are required. Additional Notes (An opinion on performance is mandatory): B. Grading and Drainage Comments: No evidence of water penetration observed at this time Water spots evident Appears to have been repaired Drainage: Additional Notes: CR Roof Covering Materials Type(s) of Roof Covering: Viewed From: Condition: Pasteners improperly installed Pasteners improperly installed<

Page 5 of 16

Prepared exclusively for Sample Report • by Donnie Thomas TREC#25486

© 2022 Gold Crown Residential and Commercial Inspections • (888) 872-9192• goldcrowninspections.com Web:

goldcrowninspections.COM

Report Identifica	tion: Inspection Address	Inspection City TX Zi	pCode	Page 6 o
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
	<u>Roof</u> Ventilation observ □ Ridge / Raf □ Vermin acti Additional Notes:	ter sag noted \Box	on: Water leaks noted	□ Previous repairs noted
	E. Walls (Interior Comments: Prevalent exterior Interior Wall: Water stain Mildew Exterior Wall Water stain	siding: Is / damage S / damage missing / blocked pairs noted	Small drywall cracks Holes Small cracks □ Rotte Damage to trim, door	 Large drywall cracks Previous repairs noted Large cracks ed / exposed wood
	Additional Notes: F. Ceilings and F <i>Comments:</i> □ Water stain □ Tiles – crac □ Vinyl dama	s / damage 🛛 🛛 🗠 ked / damaged / loose	Holes and openings e / missing Slight sloping	□ Rotting evident
Ceilings:		ye ∟.	Signt Sloping	
Floors:				
	Additional Notes: G. Doors (Interio <i>Comments:</i> Interior: Damage Holes and Rotting evi Not closing Hardware Gaskets	openings dent	Location(s): [] [] [] [] []	
	Exterior: Damaged Hollow Holes and Rotting evi Not closing Hardware Weather-st	dent g properly damage/inoperative	Location(s): [] [] [] [] [] [] [] []	
		Page 6 of	f 16	

Page 6 of 16 Prepared exclusively for Sample Report ● by Donnie Thomas TREC#25486 © 2022 Gold Crown Residential and Commercial Inspections ● (888) 872-9192● goldcrowninspections.com Web:

goldcrowninspections.COM

Report Identification: Inspection Address Inspection City TX ZipCode

I=Inspected **NI=Not Inspected** NP=Not Present **D=Deficient** I NINP D Garage Door: □ Damaged □ Bent panel □ Entry door damaged Additional Notes: H. Windows Comments: Evidence of water penetration: \Box Window inoperative \Box Cracked window Broken window □ Moisture between panes □ Missing pane □ Caulking/glazing needed Child safety latches missing Locations: [] Screens: □ Holes □ Torn Bent □ Missing Additional Notes: I. Stairways (Interior and Exterior) Comments: J. Fireplace and Chimneys Comments: Type of fireplace Fuel Source: Damper: Firebox: □ Mortar missing behind face bricks □ Mortar missing rear wall □ Soot build-up □ Cracks/Lintel □ Hearth insufficient/damage □ Poor draft evident Chimney: □ Crumbling brick □ Damaged/missing cap □ Insufficient height/clearance □ Spark arrestor missing Additional Notes: K. Porches, Balconies, Decks, and Carports Comments: □ Rotting evident □ Insect Damage □ Wood/soil contact □ Trip Hazard □ Loose boards □ Handrail/railing missing/damaged □ Areas inaccessible Note: Structural load capabilities were not inspected Additional Notes: L. Other Comments: Additional Notes:

Prepared exclusively for Sample Report • by Donnie Thomas TREC#25486

© 2022 Gold Crown Residential and Commercial Inspections • (888) 872-9192• goldcrowninspections.com Web:

goldcrowninspections.COM

I=Inspected	NI=Not Inspected	NP=Not Pr	resent	D=Deficient	
I NINP D					
		١١.	ELECTE	RICAL SYSTE	MS
	A. Service Entran	ce and Pa	nels		
	Comments:				
	Main panel location:		Improper	panel location	
	Panel Condition:			ate panel labeling	
		wires	Double-I	ugging	Defective breakers
	Type of wiring:				
	ARC Fault (Refer to ARC Outlet location		r 1	□ Missing	Not tripping
		1(3).		□ Missing	□ Not tripping
			i i	□ Missing	□ Not tripping
			[]	🗆 Missing	Not tripping
	Grounding Electroc				
				verified for bonding	
					system check by licensed electrician d complete system check by licensed
	electrician		g lound, lecc	and service and	complete system check by licensed
	olootholan				
	Additional Notes:				
	B. Branch Circuits	s, Connec	ted Devic	es, and Fixtures	6
	Type of Wiring:				
	Comments:				
	Receptacle Type:		□ 3 prong	□ aluminum w	iring observed
	Ground Fault Circu		per outlets p		
	GFCI Outlet locatio		Bathroom:	□ Missing	Not tripping
		1(0).	Kitchen:	□ Missing	□ Not tripping
			Wet Bar:	□ Missing	□ Not tripping
			Laundry:	□ Missing	Not tripping
			Garage:	Missing	Not tripping
			Exterior:	□ Missing	□ Not tripping
	GFCI Reset Location	n(c)	Dryer (pane	el) 🗆 Missing	Not tripping
	Loose / brok		ive outlet	🗆 Loose / brok	en / inoperative switch
	□ Loose / brok	•			
	Smoke detection		•	🗆 Ceil	ing fan inoperative
	Improper wir			Exposed wire□ Dou	ıble-lugging
	Reverse Pola			Open ground	
	□ Wire splices	/ open juncti	on boxes	Voltage drop	Didetected
	Additional Notes:				
	C. Other				
	Comments:				
	Additional Notes:				

Page 8 of 16

Prepared exclusively for Sample Report • by Donnie Thomas TREC#25486

© 2022 Gold Crown Residential and Commercial Inspections • (888) 872-9192• goldcrowninspections.com Web:

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	_		AND AIR-CONDITIONING SYSTEMS
	A. Heating Equip Type of Systems: Energy Sources: Comments:	ment	
		nspected but were no	side temperature is above 70°F ot operated since the ambient temperature exceeds 70°F.
	Unit 1:	nostat Location:	
	Con Filter Gas: □	dition: □ Loose Type: Condit Rust on burner Improper venting Gas leak Gas line not support ic: □ Not on	 □ Flame inconsistent □ Pilot not lit □ Copper gas line □ No gas shut-off □ Air blowing in burner chamber ted □ Drip leg missing □ Inoperable □ Limit switch missing/inoperable □ Noisy
	Additional Notes:		
	Note: Gas fired he disassembly. REC B. Cooling Equip <i>Type of System:</i> <i>Comments:</i> Heat pum	eat exchangers canno COMMEND MAINTED oment ps are operated in or oning unit(s) were ins	mend service by qualified H.V.A.C Service Company of be thoroughly inspected for deficiencies without NANCE AND SERVICE PRIOR TO USE. The mode only spected but were not operated since the ambient temperature
	cooling) Compress □ Ir Condense Condensa	or: □ Not on nproper clearance er: □ Fan not on ite Drain:	
	Secondar	Tray debris / standir y: Does not ex	
	Lo Freon line	ocation: [] : □ Insulation mis Location:	sing / damaged 🛛 Refrigerant leak possible
			mend service by qualified H.V.A.C Service Company AND SERVICE PRIOR TO USE.
		Page 9	
© 2022 Gold			t ● by Donnie Thomas TREC#25486 ns ● (888) 872-9192● goldcrowninspections.com Web:
		goldcrowninspe	
REI 7-6 (8/9/21)	Promulgate	d by the Texas Real I	Estate Commission • (512) 936-3000 • www.trec.texas.gov

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NINP D			
	C. Duct Systems Comments:	, Chases and Ve	ents
		vident (return) torn / missing	Openings evident (supply)
	Additional Notes:		
	D. Other		

Comments:

Additional Notes:

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient				
I NINP D							
	IV. PLUMBING SYSTEM						
	Location of water Location of main v Static water press Type of supply pip Comments:	vater supply valve: ure reading: [##]		ary throughout the day.			
	Fixture Shut Off V Kitchen			pray leak ow / no pressure			
		ty Sink: □ Faucet leak □ Sink leak nal Notes:		pray leak ow / no pressure			
		ty Sink: □ Faucet leak □ Sink leak nal Notes:		pray leak ow / no pressure			
	□ F Bathtu	rain leak ☐ Slow drain aucet/knob damaged ibs:	□ Stopper missing/n	-			
	□ F □ D	Prain leak	 Faucet leak Stopper missing/n Diverter non-funct Water damage 				
	□ D □ F □ D Comm □ L	Prain leak □ Slow drain aucet/knob damaged boor not closing properly nodes: oose on floor □ Fills slow	Head leak	 □ Faucet/knob missing □ Pan leak □ Grout/caulk missing erly □ Leaking 			
	Addition	lot turning off nal Notes:					
		Prain leak	□ Faucet leak □ □ Stopper missing/n	□ Faucet/knob missing on-functioning			
	□ D □ F □ D □ G	Prain leak	 Faucet leak Stopper missing/n Diverter non-funct Water damage 				
	Showe D	er: Drain leak	□ Faucet leak	□ Faucet/knob missing			
	Droporod ovolucius	Page 11 of 16	annia Thomas TDE	2425400			

Prepared exclusively for **Sample Report** ● by **Donnie Thomas TREC#25486** © 2022 Gold Crown Residential and Commercial Inspections ● (888) 872-9192● goldcrowninspections.com Web:

$gold crown in spections. {\color{black} \textbf{COM}}$

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NINP D	•			
	Π	Faucet/knob damaged	Head leak	🗆 Pan leak
		Door not closing properly	□ Water damage	□ Grout/caulk missing
		modes:		_ ••••••
		Loose on floor	Not flushing prop	perly 🗆 Leaking
		Not turning off		200
		onal Notes:		
	3rd			
		Sinks:		
		Drain leak 🛛 Slow drain	Faucet leak	□ Faucet/knob missing
		Faucet/knob damaged	□ Stopper missing	•
	Bath	5		5
		Drain leak 🛛 Slow drain	Faucet leak	□ Faucet/knob missing
		Faucet/knob damaged	□ Stopper missing	
		Diverter leak	Diverter non-fun	
		Grout/caulk missing	Water damage	5
	Shov	ver:	Ŭ	
		Drain leak 🛛 Slow drain	Faucet leak	Faucet/knob missing
		Faucet/knob damaged	Head leak	Pan leak
		Door not closing properly	Water damage	□ Grout/caulk missing
	Com	modes:	-	-
		Loose on floor D Fills slow	Not flushing prop	perly 🗆 Leaking
		Not turning off		
	Additic	onal Notes:		
	Outsid	le Faucets:		
		Leak Location:	ront 🛛 Rear	□ Side
		Inoperative	ront 🛛 Rear	□ Side
		Missing/broken handle	ront 🛛 Rear	□ Side
		Missing anti-siphon	ront 🛛 Rear	□ Side
	Additic	onal Notes:		
	B. Drain, Waste	s and Vents		
	Type of drain pip	oing material:		
	Comments:			
	Additional Notes			
	C. Water Heatin	a Fauinment		
		g Equipment		
	Energy Source:			
	Capacity: Comments:			
		to OP-I form)		
	Unit 1:	,		
	Locatio			
		Pan and Drain Installed:		
		e Unit(s): Physically Protected:	18 inch Floor Clear	ance: Corrosion at supply
	conne			
	Leak			
		erature & Relief Valve (TPR):		
	<u></u>			
	<u>Gas U</u>	nit:		
		hut Off Valve:	Branch Line:	
			Eranon Ento.	
	Dropored avaluat	Page 12 of 16	nnia Thomas Th	
		ely for Sample Report • by Do		
	TOWIT RESIDENTIAL AND	Commercial Inspections • (888		owninspections.com web:

goldcrowninspections.COM

Page	13	of	16
· age			

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NINP D				
	Imprope	r venting:	Drip leg missing	
	Electric I	Jnit: Improper wiring:	Inoperative heating element:	
	Additional Notes:			
	D. Hydro-Massaq	e Therapy Equipment		
	Comments: GFCI condition: Undersic □ Leak	GFCI Reset Location: le of tub readily accessible: Switches loose s in port openings	□ Unsafe location	
	Additional Notes:			
	Location of gas me	on System and Gas Ap eter: ution piping material:	opliances	
	Additional Notes:			
	F. Other			
	Comments:			
	Additional Notes:			

		D=Deficient	lesent	NP=Not P	NI=Not Inspected	I=Inspected
	FS		V. APP			I NINP D
d	sing □Noisy	Ih loop missing	< 🗆 Hig	sted @ [##]° □ Leal fective □ Rus	A. Dishwashers Comments: Checked and tea Inoperative Soap tray de Loose in cab	
d	 Poorly secured Damaged splash guard 		□ Stuck hamr □ Noisy	Disposers	Additional Notes: B. Food Waste <i>Comments:</i> □ Inoperative □ Vibration	
	□ Inoperative □ Noisy		st Systems Vents into attic No Light	j 🗆	Additional Notes: C. Range Hood <i>Comments:</i> □ Filter Missing □ Damaged sw	
Left rear Left rear	ront	□ Left front □ Left front □ Left front door latch erative	Type of Branc Gas Right front Right front Right front Right front Inoperative Clock inope Achieved: Ove	Cooktop: alve: shut-off in roon off pilot nissing knobs g amage ative light	Cooktop:	
erable	□ Microwave inoperable /damaged	damage le missing/dan	□ Door seal o □ Door hand		Additional Notes: E. Microwave C <i>Comments:</i> □ Light inop □ Does not	
	ust fan light inoperative ensation / vent problems tion mas TREC#25486	□ Exhaust f □ Condens neater location onnie Thoma	 □ Noisy □ Damaged □ Improper h Page 14 of 16 Report ● by D 	an inoperative ssing operative rely for Sample	Cover mis Heater ind Prepared exclusiv	
Lef Lef tior	 ☐ Inoperative ☐ Noisy ☐ Anti-tip missing ront ☐ Right rear ☐ Left ront ☐ Right rear ☐ Left rear ☐ Left ront ☐ Right rear ☐ Left ront ☐ Right rear ☐ Left ront ☐ Right rear ☐ Left re	of Oven: th Line: s leak Left front Left front Left front door latch erative en 1 [##]°F damage le missing/dam room Heate Exhaust f Condens heater location onnie Thomas	St Systems Vents into attic No Light Ovens Type of Branc I Gas Right front Right front Right front Right front Right front Clock inope Achieved: Oven Achieved: Oven tial	g I vitches I oktops, and I oktops, and I cooktop: I alve: shut-off in room off pilot I nissing knobs g amage I ative light I at set at 350°F I ligh/low differer I Ovens I berative heat properly Exhaust Ven I an inoperative I operative I I I I I I I I I	C. Range Hood Comments: Filter Missing Damaged sw Additional Notes: D. Ranges, Coo Comments: Type of Range/C Gas Shut Off Va No gas Cooktop: Not lighting Damaged/m Improper heating Oven: Door da Inopera Thermosta Thermosta E. Microwave C Comments: Light inop Does not Additional Notes: F. Mechanical I Cover mis Heater ind Prepared exclusiv	

goldcrowninspections.COM

Report Identification: Inspection Address Inspection City TX ZipCode

Additional Notes:

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NINP D				
	Additional Notes:			
	G. Garage Door Operators Comments: Auto reverse block test acceptable: Electric eye reverse test acceptable: Improper sensor height (more than six inches above garage floor) Opener Inoperative Opener Damaged			
	Additional Notes: H. Dryer Exhaus <i>Comments:</i>	t Systems		
	Additional Notes: I. Other <i>Comments:</i>			

Page 15 of 16

I=Inspected	NI=Not Inspected NP=Not Present D=Deficient
	VI. OPTIONAL SYSTEMS A. Landscape Irrigation (Sprinkler) Systems Comments:
	 B. Swimming Pools, Spas, Hot Tubs and Equipment Type of Construction: Comments: Gingle Main Drain (potential entrapment hazard) GFCI Device Required (protect Pool/Spa light and other outlets)
	C. Outbuildings Comments: □ Improper sensor height (more than six inches above garage floor)
	D. Private Water Wells (A coliform analysis recommended.) Type of Pump: Type of Storage Equipment: Comments: Location of Well: System tested: minutes Type of Well: Coliform test performed by [] Drip leg missing on gas heater
	E. Private Sewage Disposal Systems Type of System: Location of Drain Field: Comments: System presently in use:
	F. Other Built-in Appliances Comments:
	G. Other: Comments: